

## **Evaporation Source Selection Guide**

## **Process Conditions**

	F									
Evaporation Source Type	Low Power <100 amps	Med. Power 100-250 amps	High Power >250 amps	Low temp Materials <1,000°C	High temp Materials >1,000°C	Corrosive Materials	Low Volume Coating <1,000A°	Medium Volume Coating 1,000A° - 5,000A°	High Volume Coating >5,000A°	Reduce Particulates from Spitting
Tungsten Filament										
Tungsten Point Source										
Tungsten Basket										
Alumina Coated Basket										
Tungsten Basket Heater										
Shielded Crucible Heater										
Evaporation Boat										
Folded Boat										
Alumina Coated Boat										
Baffled Box Source										
Shielded Baffled Box Source										
Micro-Electronic Source										
Chrome Plated Tungsten Rod										

<sup>©</sup> Copyright R. D. Mathis Company

This source selection guide is provided to help you determine which evaporation source type might fit your needs the best.

## How to use the Guide:

- 1) Determine how much current your system power supply is capable of safely producing.
- 2) Establish the vapor temperature of the material(s) you plan on evaporating.
- 3) Estimate the coating thickness you will be attempting.

With the information shown above, you can select which source types will best meet your needs. The actual power required for each part number can be found on our website by clicking on the part number. As always, the R. D. Mathis company offers no charge technical support if you need further assistance in choosing the right evaporation source to make your thin film coating process a success.

© Duplication, reproduction or copying of the information contained in this selection guide is not permitted without the express written consent of the R. D. Mathis Company.

We are specialists in the custom fabrication of Hi-Vacuum evaporation sources with complete and highly flexible refractory facility. Our comprehensive catalog is available upon request.